

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CP464
NNE
1/2-1
0.730 mi.
3852 ft.

TRI-TECH AUTO SERVICE
TRI-TECH AUTO-SER./EXXON
BROOKLYN, NY

NY LTANKS S106703193
N/A

Site 1 of 2 in cluster CP

Relative:
Higher

Actual:
13 ft.

LTANKS:

Name: TRI-TECH AUTO SERVICE
Address: TRI-TECH AUTO-SER./EXXON
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 8709866 / 2003-03-17
Facility ID: 8709866
Site ID: 111256
Spill Date: 1988-02-21
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: A3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 1988-02-22
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1988-02-24
Spill Record Last Update: 2003-03-17

Spiller Name: Not reported
Spiller Company: ISLAND TRANSPORTATION
Spiller Address: 299 EDISON AVENUE
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 97319
DEC Memo: ""

Remarks: "STICK LINE WAS NOT TIGHT AND DRIVER MADE MISCALCULATION AND RESULTED IN THE SPRAYING AND OVERFILL OF TANK."

All Materials:

Site ID: 111256
Operable Unit ID: 914804
Operable Unit: 01
Material ID: 461660
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 65.00
Units: G
Recovered: .00
Oxygenate: Not reported